March

3/18/2021: The cooler on the 7900x needs to be shifted over so that it covers the IHS more completely before you run linpack etc. on it. Ram slots A1, A2, B1, B2 are the ones that work (e.g. all ram slots left of cpu socket.

Revision #1

Created Fri, Mar 19, 2021 12:22 AM by kenneth

Updated Fri, Mar 19, 2021 12:23 AM by kenneth